



BONGAON MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
DUTTA PARA, BONGAON	23.0393979 88.8349709	16	MAHENDRA DUTTA PRATHAMICK VIDYALAYA	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	1	1	1	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	178	116	178	4856	BONGAON	

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-01-27
Nearest location of CT/PT (approx)	DUTTA PARA, BONGAON
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	1
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	O& M by school authority

Name: Sankar Majumder

Designation: SAE

Contact No: 9002997440

Date: _____

Name: Suprimo Ghosh

Designation: Civil Engineer

Signature with stamp

Checked & Verified

Suprimo Ghosh 23/1/26
Engineer (Civil)
Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration

Site Image

