



DUBRAJPUR MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
NEAR BADAMBARI BAURIPARA	23.8075718 87.3796159	1	0.05	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	842	106	842	1741	ASUDALLA	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-11-20
Nearest location of CT/PT (approx)	NEAR BADAMBARI BAURIPARA
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	22.7 SqM
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	User Group
Remarks	Ok

Name: Debkanta Saha

Designation: Other

Contact No: 8145890322

Date: _____

Name: Abhik Majumdar

Designation: Civil Engineer

Signature with stamp

A.E (UDSSMT)
DUBRAJPUR MUNICIPALITY
Dubrajpur, Birbhum

Checked & Verified

As per...
Engineer (Civil)

Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration

Site Image

