



HABRA MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Rajbari more bazar unnayan committee	22.8322707 88.6688103	11	0.0027	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	3	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	NA	82	56	5287	NAGARTHUBA	



Visit Date	2025-12-04
Nearest location of CT/PT (approx)	Rajbari more bazar unnayan committee
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model
Male Toilet Seats	
Female Toilet Seats	
Male Urinal	3
Female Urinal	
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	
No Of Urinal Seats	
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	O&M by Bazar unnayan committee

Name: Pankaj Ghosh

Designation: SAE

Contact No: 7679434985

Date: _____

Name: Suprimo Ghosh

Designation: Engineer

Signature with stamp

Suprimo Ghosh
04/12/25

Sub-Assistant Engineer
HABRA MUNICIPALITY

Suprimo Ghosh 4/12/25

Signature with stamp assigned by Hijli Inspiration



