



HABRA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Matuya sampradaya	22.8162296 88.6339811	24	0.0033	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	3	2

Land Details

Classification	Plot No.	JI No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	NA	85	1041	548	HARIA	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-12-04
Nearest location of CT/PT (approx)	Matuya sampradaya
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Not available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	Cancel due to insufficient land

Name: Pankaj Ghosh

Designation: SAE

Contact No: 7679434985

Date: _____

Name: Suprimo Ghosh

Designation: Engineer

Signature with stamp

Pankaj Ghosh
04/12/25

**Sub-Assistant Engineer
HABRA MUNICIPALITY**

Suprimo Ghosh 4/12/25

Signature with stamp assigned by Hijli Inspiration



Site Image

