



BAIDYABATI MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
The Sheoraphuli Club, 129, N.C.Ghosh Sarani, Sheoraphuli, Hooghly	22.7720875 88.3261913	10	22.5	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	1	1	2	1

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	129	6	610	2906	Sheoraphuli	

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-01-21
Nearest location of CT/PT (approx)	The Sheoraphuli Club, 129, N.C.Ghosh Sarani, Sheoraphuli, Hooghly
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	O&M by club authority

Name: Ujjwal Seth

Designation: SAE

Contact No: 7980428592

Date: _____

Name: Suprimo Ghosh

Designation: Civil Engineer


Signature with stamp

Useth
Sub-Assistant Engineer
Baidyabati Municipality

Checked & Verified

Suprimo Ghosh
Signature with stamp assigned by Hjjt Inspiration

Site Image



Useth
Sub-Assistant Engineer
Baidyabati Municipality