



DINHATA MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
SANHATI MAIDAN	26.1371958 89.4613377	3	SANHATI MAIDAN	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	3	3	4	4



Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	7124	108	7124	3956	DINHATA	

Appendix 1 - Road Site Inspection Report

Site Name	
Location	
Inspector	
Date	
Time	
Weather	
Wind	
Temperature	
Humidity	
Visibility	
Soil Type	
Groundwater Level	
Vegetation	
Adjacent Properties	
Other Notes	
Remarks	

Name: _____
 Designation: _____
 Contact No: _____
 Date: _____
 Name of the Engineer: _____
 Designation: _____

Signature with stamp
Checked & Verified

Engineer (Civil)
 Signature with stamp assigned by HOD/Inspector

Sub Assistant Engineer
District Municipality

