



BAIDYABATI MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Saraswat Sangha Chatra Lankar Bagan, Serampore , Hooghly	22.7608712 88.3317231	2	35.7	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	3	2

Land Details

Classification	Plot No.	JI No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	39(29)	10	7885	592/27	Chatra	

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-01-21
Nearest location of CT/PT (approx)	Saraswat Sangha Chatra Lankar Bagan, Serampore , Hooghly
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No G ✓
Male Toilet Seats	2
Female Toilet Seats	2
Male Urinal	3
Female Urinal	2
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	4
No Of Urinal Seats	5
total Baths	0
Bath	0
Area	7m x 5.1m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	O & M by club authority

Name: Ujjwal Seth

Designation: SAE

Contact No: 7980428592

Date: _____

Name: Supremo Ghosh

Designation: Civil Engineer

Signature with stamp

U Seth
**Sub-Assistant Engineer
 Baidyabati Municipality**

Checked & Verified

Signature with stamp assigned by Hill Inspiration

Supremo Ghosh

HILL INSPIRATION

Site Image



Lat: 22.7607932
Long: 88.3316824
Location: Dakshin Rajyadharpur,



Lat: 22.7607797
Long: 88.3316909
Location: Dakshin Rajyadharpur,

Uetb
Sub-Assistant Engineer
Baidyabati Municipality