



BAIDYABATI MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Chatra Shisu Samity, Chatra Sitalatala ,(6no railgate),Serampore, Hooghly	22.7637463 88.332832	2	35.7	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	3	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	1972	10	4353	1693/16	Chatra	

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-01-21
Nearest location of CT/PT (approx)	Chatra Shisu Samity, Chatra Sitalatala ,(6no railgate),Serampore, Hooghly
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specify)
Remarks	O&M by club authority

Name: Ujjwal Seth

Designation: SAE

Contact No: 7980428592

Date: _____

Name: Suprimo Ghosh

Designation: Civil Engineer

Signature with stamp

Useth
Sub-Assistant Engineer
Baidyabati Municipality
 Checked & Verified

Signature with stamp assigned by Hiji Inspiration

Suprimo Ghosh
 Engineer (Civil)
 Hiji Inspiration

Site Image



Useth
Sub-Assistant Engineer
Baidyabati Municipality