



DUBRAJPUR MUNICIPALITY
JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
BAIRAGIKONDA NEAR CHRISTIAN SCHOOL	23.8089738 87.3781264	1	0.03	Acre

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Danga	1/646	138	1/646	566	JANGAL DUBRAJPUR	

Annexure-III (Joint Site Inspection Report)

Visit Date	2025-12-24
Nearest location of CT/PT (approx)	BAIRAGIKONDA NEAR CHRISTIAN SCHOOL
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No G
Male Toilet Seats	2
Female Toilet Seats	2
Male Urinal	3
Female Urinal	2
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	4
No Of Urinal Seats	5
total Baths	0
Bath	0
Area	7m x 5.1m
Cubical Male	1200 x 1000mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Submersible pump
Operation and Maintenance Plan	Other (specify)
Remarks	Maintain by Institution.A submersible pump will be arranged by Institution.

Name: Rohit Sethia

Designation: SAE

Contact No: 9832530829

Date: _____

Name: Suprimo Ghosh

Designation: Civil Engineer

Signature with stamp

S.A.E (UIDSSMT)
 DUBRAJPUR MUNICIPALITY
 Dubrajpur, Birbhum

Checked & Verified

Suprimo Ghosh


Engineer (Civil)

Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration

24/12/25

Site Image



Lat: 23.8109036
Long: 87.4044812
Location: Bhabanipur, West



Lat: 23.8109036
Long: 87.4044812
Location: Bhabanipur, West