



BAIDYABATI MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Genrir Danga Milan Samity	22.7780687 88.3180696	8	35.7	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	3	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Bastu	45622	6	247	2522	Sheoraphuli	



Annexure-III (Joint Site Inspection Report)

Visit Date	2026-01-30
Nearest location of CT/PT (approx)	Genrir Danga Milan Samity
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	3
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	Other (specifv)

Ujeth
Sub-Assistant Engineer
Baidyabati Municipality

Checked & Verified
A. Munda
Engineer (Civil)
Hijli INSPIRATION

Site Image



Useth
Sub-Assistant Engineer
Baidyabati Municipality

Checked & Verified
Anajudo
Engineer (Civil)
Hiji INSPIRATION