



## KALIMPONG MUNICIPALITY

### JOINT SITE INSPECTION REPORT

#### Annexure-III

#### Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
PHUNCHOG SANGNAG TAGTEN LING BUDDHIST WELFARE & CULTURAL CENTRE	27.064351 88.4688653	1	TAMANG GUMBA, NEAR HIMALAYAN HOTEL	Sq/Meter

#### Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
PT (Public Toilet Project)	2	2	2	2

#### Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	N/A	56	N/A	N/A	KALIMPONG TOWN	

#### Annexure-III (Joint Site Inspection Report)

Visit Date	2026-02-18
Nearest location of CT/PT ( approx )	PHUNCHOG SANGNAG TAGTEN LING BUDDHIST WELFARE & CULTURAL CENTRE
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	ULB Model

Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	
Female Bath	
Children Feed	
Children Feed	
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	
Bath	
Area	
Cubical Male	
Cubical Female	
Cubical Urinal Seat Size	
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water
Operation and Maintenance Plan	User Group
Remarks	Ok

*M. Rai*  
19/2/20  
Sub Assistant Engineer  
Kalimpong Municipality

Name: Mandira Rai

Designation: SAE

Contact No: 9002986852

Date: \_\_\_\_\_

Name: Abhik Majumdar

Designation: Civil Engineer

Contact No: 9851301709

Date: \_\_\_\_\_


Signature with stamp

Checked & Verified  
*Abhik Majumdar*  
Engineer (Civil)  
Hijli INSPIRATION

*Abhik Majumdar*  
Co-ordinator  
Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration

Site Image



Lat: 27.0643637  
Long: 88.4689933  
Location: Kalimpong, Kalimpong Khasmahal



Lat: 27.064355  
Long: 88.4690244  
Location: Kalimpong, Kalimpong Khasmahal

[Download PDF](#)