



KALIMPONG MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
K.D.Pradhan Road football centre of	27.075361 88.4736321	4	1	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
CT (Community Toilet Project)	2	2	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	1	1	1	1	1	

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-02-17
Nearest location of CT/PT (approx)	K.D.Pradhan Road football centre of
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F

Male Toilet Seats	1
Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water)
Operation and Maintenance Plan	Other (specify)
Remarks	Toilet maintenance by club

Name: 9002986852 Mandira Rai

Designation: SAE

Signature with stamp

Contact No: 9002986852

Date: _____

Name: Abhik Majumdar

Abhik Majumdar

Designation: Civil Engineer

Co-ordinator
Hijli INSPIRATION

Signature with stamp assigned by Hijli Inspiration

Contact No: 9851301709



Date: _____

Checked & Verified

Mandira Rai
Engineer (Civil)
Hijli INSPIRATION

M. Rai
Sub Assistant Engineer
Kalimpong Municipality

Site Image



[Download PDF](#)
