



KALIMPONG MUNICIPALITY

JOINT SITE INSPECTION REPORT

Annexure-III

Location Details

Name of the Location	Latitude & Longitude	Ward	Area	Area Unit
Sadhu sundar sing rotary centre	27.0756033 88.4743688	4	share Girl's Football Academy, k.d pradhan road kalimpong	Sq/Meter

Project Details

Proposed Project Type	Toilet Seat (Male)	Toilet Seat (Female)	Urinal Seat (Male)	Urinal Seat (Female)
Institutional Toilet Block	2	2	2	2

Land Details

Classification	Plot No.	Jl No.	Dag No.	Khatian No.	Mouza	Possession Details (Owned by)
Other	N/A	N/A	N/A	N/A	N/A	

Annexure-III (Joint Site Inspection Report)

Visit Date	2026-02-17
Nearest location of CT/PT (approx)	Sadhu sundar sing rotary centre
Toilet Type (Aspirational/Normal)	Normal Toilet
Model Name	CT/PT - Model No F
Male Toilet Seats	1

Female Toilet Seats	1
Male Urinal	2
Female Urinal	1
Male Bath	0
Female Bath	0
Children Feed	0
Children Feed	0
No Of Toilet Seats	2
No Of Urinal Seats	3
total Baths	0
Bath	0
Area	5m x 4.5m
Cubical Male	1200 x 1000 mm
Cubical Female	1600 x 1200 mm
Cubical Urinal Seat Size	600/500
Space for Soakpit/Soak Well	Available
Water Availability (Details)	Piped water supply (in detail) - (Municipal Pipe water)
Operation and Maintenance Plan	Other (specify)
Remarks	Toilet maintenance by institutions

Name: Mandira Rai

Designation: SAE

Contact No: 9002986852

Date: _____

Name: Abhik Majumdar

Designation: Civil Engineer

Contact No: 9851301709

Date: _____

Mandira Rai
 Sub Assistant Engineer
 Signature with stamp
 Kalimpong Municipality

Abhik Majumdar
 Co-ordinator
 Hiji INSPIRATION

Checked & Verified
Abhik Majumdar
 Engineer (CIVIL)
 Hiji INSPIRATION
 Signature with stamp assigned by Hiji Inspiration

Site Image



Lat: 27.0753653
Long: 88.4744026
Location: Kalimpong, Chotta Bhalukhop



Lat: 27.0757405
Long: 88.4741798
Location: Kalimpong, Chotta Bhalukhop

[Download PDF](#)
